


I Втулки переходные

Тип С



(мм)

Обозначение	ØD	Ød	ØC	L
C20 - 6 (1/4")	20	6(1/4")	26	55
- 8 (5/16")	20	8(5/16")	26	55
- 10 (3/8")	20	10(3/8")	26	55
- 12(1/2")	20	12(1/2")	26	55
- 14	20	14	26	55
- 16 (5/8")	20	16(5/8")	26	55
C 32 - 6 (1/4")	32	6(1/4")	38	70
- 8 (5/16")	32	8(5/16")	38	70
- 10 (3/8")	32	10(3/8")	38	70
- 12 (1/2")	32	12(1/2")	38	70
- 14	32	14	38	70
- 16 (5/8")	32	16(5/8")	38	70
- 19 (3/4")	32	19(3/4")	38	70
- 20	32	20	38	70
- 25 (1")	32	25(1")	38	70
C 42 - 6 (1/4")	42	6(1/4")	48	75
- 8 (5/16")	42	8(5/16")	48	75
- 10 (3/8")	42	10(3/8")	48	75
- 12 (1/2")	42	12(1/2")	48	75
- 14	42	14	48	75
- 16 (5/8")	42	16(5/8")	48	75
- 19 (3/4")	42	19(3/4")	48	75
- 20	42	20	48	75
- 25 (1")	42	25(1")	48	75
- 32(1 1/4")	42	32(1 1/4")	48	75

