


# HRMDS09



(мм)

Обозначение		øD	ød	l	L	ap	
<b>HRMDS 0940HR-4M40</b>	4	40	40	130	250	1.5	2.2
<b>0940HR-4L40</b>	4	40	40	180	300	1.5	2.7
<b>0940HR-4S42</b>	4	40	42	60	150	1.5	1.4
<b>0940HR-4M42</b>	4	40	42	130	250	1.5	2.3
<b>0940HR-4L42</b>	4	40	42	180	300	1.5	2.8
<b>0950HR-4S32</b>	4	50	32	40	150	1.5	1.1
<b>0950HR-4M32</b>	4	50	32	40	250	1.5	1.6
<b>0950HR-4L32</b>	4	50	32	40	300	1.5	2
<b>0950HR-4S40</b>	4	50	40	40	150	1.5	1.4
<b>0950HR-4M40</b>	4	50	40	40	250	1.5	2.4
<b>0950HR-4L40</b>	4	50	40	40	300	1.5	2.9
<b>0950HR-4S42</b>	4	50	42	40	150	1.5	1.6
<b>0950HR-4M42</b>	4	50	42	40	250	1.5	2.6
<b>0950HR-4L42</b>	4	50	42	40	300	1.5	3.1
<b>0950HR-5S32</b>	5	50	32	40	150	1.5	1.1
<b>0950HR-5M32</b>	5	50	32	40	250	1.5	1.6
<b>0950HR-5L32</b>	5	50	32	40	300	1.5	2
<b>0950HR-5S40</b>	5	50	40	40	150	1.5	1.4
<b>0950HR-5M40</b>	5	50	40	40	250	1.5	2.4
<b>0950HR-5L40</b>	5	50	40	40	300	1.5	2.9
<b>0950HR-5S42</b>	5	50	42	40	150	1.5	1.6
<b>0950HR-5M42</b>	5	50	42	40	250	1.5	2.6
<b>0950HR-5L42</b>	5	50	42	40	300	1.5	3.1

## Применяемые СМП

WNMX-MM



Обозначение	Тв. сплав с покрытием								Кермет			Тв. сплав				Стр.		
	NCM325	NCM335	NC5330	PC3500	PC5300	PC5400	PC3545	PC9530	PC6510	PD2000	CN2000	CN20	CN60	H01	G10		ST30A	ST20
WNMX 09T316ZNN-MM				●	●	●	●	●										E23

## Комплектующие



ФТКА0307

TW09S