

Е Концевые фасочные фрезы

ССТ *New*




Рис. 1




Рис. 2

(мм)

Обозначение	$\varnothing D = \varnothing d$	$\varnothing D_1$	L	θ°	Рис.	
ССТ060 -	030	3	40	60°	1	
	040	4	40			
	060	6	50			
	080	8	60			
	100	10	70			
	120	12	80			
ССТ060Т -	030	3	40		60°	2
	040	4	40			
	060	6	50			
	080	8	60			
	100	10	70			
	120	12	80			
ССТ060Т -	030L	3	100	60°		2
	040L	4	100			
	060L	6	100			
	080L	8	120			
	100L	10	120			
	120L	12	150			
ССТ090 -	030	3	40		90°	1
	040	4	40			
	060	6	50			
	080	8	60			
	100	10	70			
	120	12	80			
ССТ090Т -	030	3	40	90°		2
	040	4	40			
	060	6	50			
	080	8	60			
	100	10	70			
	120	12	80			
ССТ090Т -	030L	3	100		90°	2
	040L	4	100			
	060L	6	100			
	080L	8	120			
	100L	10	120			
	120L	12	150			
ССТ120 -	030	3	40	120°		1
	040	4	40			
	060	6	50			
	080	8	60			
	100	10	70			
	120	12	80			
ССТ120Т -	030	3	40		120°	2
	040	4	40			
	060	6	50			
	080	8	60			
	100	10	70			
	120	12	80			
ССТ120Т -	030L	3	100	120°		2
	040L	4	100			
	060L	6	100			
	080L	8	120			
	100L	10	120			
	120L	12	150			

Концевые фасочные фрезы



Фрезерование

Е