


I Патроны фрезерно4сверлильные серии NPM

DBT-NPM



(мм)

Обозначение	ØD	L	ØC	H	G	Втулка переходная	 kg
DBT30 - NPM20 - 85	20	85	54	85	M12	CS20, C20	0.8
DBT40 - NPM20 - 85	20	85	54	85	M16	CS20, C20	1.5
100	20	105	54	85	M16	CS20, C20	1.9
135	20	135	54	85	M16	CS20, C20	2.3
NPM32 - 110	32	110	75	95	M16	CS32, C32	2.5
120	32	120	75	95	M16	CS32, C32	3.1
135	32	135	75	95	M16	CS32, C32	3.3
DBT50 - NPM20 - 105	20	105	54	85	M16	CS20, C20	1.7
135	20	135	54	85	M16	CS20, C20	2.0
165	20	165	54	85	M16	CS20, C20	2.4
NPM32 - 110	32	110	75	105	M24	CS32, C32	4.8
135	32	135	75	105	M24	CS32, C32	5.3
165	32	165	75	105	M24	CS32, C32	6.3
NPM42 - 110	42	110	90	125	M24	CS42, C42	5.4
135	42	135	90	125	M24	CS42, C42	6.0
165	42	165	90	125	M24	CS42, C42	7.3

